



3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535616

Date Completed
2024-05-30

Work Order Type
Service

Person
Jason Pogue

<https://www.westerraequipment.com/>

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: DHKCEADYAN0001203
Make: DEVELON
Model: DX35Z-7-US20
Meter: 357.0
Unit No.: 126154 / Internal No.: 126154

Labels

Internal, Shop

Description

UEI INSPECTION-

- Perform Used Equipment Inspection (UEI) max 2 hrs
- Add Westerra/Williams Decals - if required
- Note size of attachment(s) AND stock numbers returned with unit(no barcode)- use paint pen to identify. Yard personal can tag with proper sticker(s)once UEI is completed
- Take pictures (front/back/side/inside cab) follow PDF guidelines
- UPDATE HOURS!
- Please upload the UEI reports and Photos on the SharePoint

Work Performed

Bring unit to shop
Test functions
Check over
Pictures taken
2 buckets with unit, 1x 18" dig & 1x 36" clean out
Equipped with thumb, pin grabber and thumb/aux hand valve
Check fluid levels - hyd oil needs to be topped up
Check for leaks - loose fittings at couplers
Check undercarriage - good
Coupler hoses should be loosened and adjusted to prevent getting pinched
Should at least have a 500 service done, or 1000/6month
Check for damage - coupler tubeline bent; paint damage on blade, buckets and thumb; boom cylinder shield bent
Rattle in rear rh corner of cab - remove panel, check for loose retainers and add foam if needed

By. Jason Pogue, Date: 2024-05-28

Parts

Date	Description	Quantity
------	-------------	----------

Travel & Labor

Date	Person	Type
2024-05-28	Jason Pogue	LABOR



**Westerra
Equipment**

A WESGROUP EQUIPMENT COMPANY

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535616

Date Completed
2024-05-30

Work Order Type
Service

Person
Jason Pogue

<https://www.westerraequipment.com/>

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: DHKCEADYAN0001203
Make: DEVELON
Model: DX35Z-7-US20
Meter: 357.0
Unit No.: 126154 / Internal No.: 126154

Customer Name: Kourtney Vitcoe

By signing below, the signer agrees the work above has been completed. The customer will receive an invoice separately which is due and payable as per the terms specified.
Thank you for your business!

Kourtney Vitcoe



A WESGROUP EQUIPMENT COMPANY

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535616

Date Completed
2024-05-30

<https://www.westerraequipment.com/>

Work Order Type
Service

Person
Jason Pogue

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: DHKCEADYAN0001203
Make: DEVELON
Model: DX35Z-7-US20
Meter: 357.0
Unit No.: 126154 / Internal No.: 126154

OK = Completed & OK

ADJUST = Adjustment Needed

REPAIR = Repair / Replace

URGENT - Needs Immediate Attention

NA = Not Applicable

Checklist

1. PPE Check

- | | |
|--|----|
| 1. Are You Wearing Hi-Vis | OK |
| 2. Are You Wearing Eye Protection | OK |
| 3. Is The Area You Are Working In Free From Hazard | OK |
| 4. Is A Hard Hat Required For Work Being Perf | NA |
| 5. Are You Up To Date With OK Alone | NA |

2. Safety Checks

- | | |
|--------------------------------|----|
| 1. Hydraulic Lock Out Function | OK |
| 2. Cab Condition | OK |
| 3. Workgroup | OK |
| 4. Counterweight Bolts | OK |
| 5. Hood Latch | OK |
| 6. Safety Decals | OK |
| 7. Handles & Steps | OK |
| 8. Operator Seat | OK |
| 9. Operator Seat Belt | OK |
| 10. Operator Seat Bar | OK |
| 11. Horn Operation | OK |
| 12. Back Up Alarm | OK |
| 13. Wiper Motor / Arm / Blade | OK |
| 14. Warning Beacons & Lights | OK |

3. Operation Checks

- | | |
|------------------------------------|----|
| 1. Power Train Performance | OK |
| 2. Steering Operation | OK |
| 3. Auxiliary & Hydraulic Operation | OK |

4. Visible Leaks

REPAIR

4. Engine Checks

- | | |
|------------------------------|----|
| 1. Engine Oil And Filter | OK |
| 2. Air Filter & Inlet | OK |
| 3. Cooling Package Operation | OK |
| 4. Coolant Level Check | OK |
| 5. Coolant Condition | OK |
| 6. Drive Belt | OK |
| 7. Ancillary Belts | OK |
| 8. Clamps & Hardware | OK |
| 9. Exhaust | OK |

5. Hydraulic System Checks

- | | |
|--|--------|
| 1. Oil Level (All Cylinders Retracted) | ADJUST |
| 2. All Cylinders For Leaks & Chrome Wear | OK |
| 3. All Hoses For Leaks, Damage, Wear | OK |

6. Driveline Checks

- | | |
|----------------------------|----|
| 1. Sprocket Check | OK |
| 2. Track Check | OK |
| 3. Idlers Check | OK |
| 4. Rollers Check | OK |
| 5. House Swing Operation | OK |
| 6. Rotex Bearing | OK |
| 7. Forward & Reverse Speed | OK |

7. Steering Checks

- | | |
|-----------------------|----|
| 1. Tracking | OK |
| 2. Travel Lever Check | OK |
| 3. 2 Speed Operation | OK |

8. Electrical System Checks

- | | |
|------------------------------------|----|
| 1. Check & Clean Battery Terminals | OK |
|------------------------------------|----|

- | | |
|--------------------------------------|----|
| 2. Start & Charging Systems | OK |
| 3. Instrument Clusters | OK |
| 4. All Switch Operations | OK |
| 5. Pull & Save Codes (Report If Any) | OK |

9. Bobtach

- | | |
|---|----|
| 1. Main Pins & Bushings | OK |
| 2. Stick Pins & Bushings | OK |
| 3. X Change Pins & Bushings | OK |
| 4. Visible Cracks & Damage | OK |
| 5. Quick X Change Operation (If Equipped) | OK |



3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535616

Date Completed
2024-05-30

Work Order Type
Service

Person
Jason Pogue

<https://www.westerraequipment.com/>

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: DHKCEADYAN0001203
Make: DEVELON
Model: DX35Z-7-US20
Meter: 357.0
Unit No.: 126154 / Internal No.: 126154

Checklist Comments

Question

Section: 3. Operation Checks

4. Visible Leaks

Notes/Comments

Aux coupler fittings loose at hand valve

Section: 5. Hydraulic System Checks

1. Oil Level (All Cylinders Retracted)

Needs top up