



3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535758

Date Completed
2024-06-24

Work Order Type
Service

Person
Todd Richardson

<https://www.westerraequipment.com/>

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: 29722
Make: KUBOTA
Model: SVL75-2
Meter: 2792.7
Unit No.: 29722 / Internal No.: 29722

Labels

Internal, Shop

Description

UEI INSPECTION-

- Perform Used Equipment Inspection (UEI) max 2 hrs
- Add Westerra/Williams Decals - if required
- Note size of attachment(s) AND stock numbers returned with unit(no barcode)- use paint pen to identify. Yard personal can tag with proper sticker(s)once UEI is completed
- Take pictures (front/back/side/inside cab) follow PDF guidelines
- UPDATE HOURS!
- Please upload the UEI reports and Photos on the SharePoint

Work Performed

Locate unit and bring into shop

Please note this is not something we typically work on and I am not familiar with these units extra time spent to locate items in checklist

Check over unit , go through checklist

Please note front door roller/sliders are worn out and makes the door difficult to open / close

Tracks appear to be in good condition

Slight grinding noise when traveling , not familiar with these units this may be normal

No major issues noted

Check for leaks none noted

No codes on display

Unit has bucket attached , no identifying tag on bucket , sticker with # is damaged as well

Measured bucket , its 68" wide , step on front is damaged , bottom of bucket is bowed / dented , cutting edge worn in corners and has been flipped already recommend replacement

Not sure what position to have the plugs in for rear travel motors , did not check

Please note unit has multiple "double r " rental decals , but out of time on work order , not able to remove decals

By: Todd Richardson, Date: 2024-06-21

Parts

Date	Description	Quantity
------	-------------	----------

Travel & Labor

Date	Person	Type
------	--------	------



A WESGROUP EQUIPMENT COMPANY

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
134535758

Date Completed
2024-06-24

<https://www.westerraequipment.com/>

Work Order Type
Service

Person
Todd Richardson

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: 29722
Make: KUBOTA
Model: SVL75-2
Meter: 2792.7
Unit No.: 29722 / Internal No.: 29722

2024-06-21 Todd Richardson LABOR

Customer Name: Kourtney Vitcoe

By signing below, the signer agrees the work above has been completed. The customer will receive an invoice separately which is due and payable as per the terms specified.
Thank you for your business!

Kourtney Vitcoe

<https://www.westerraequipment.com/>

Work Order Type
Service

Person
Todd Richardson

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: 29722
Make: KUBOTA
Model: SVL75-2
Meter: 2792.7
Unit No.: 29722 / Internal No.: 29722

OK = Completed & OK ADJUST = Adjustment Needed REPAIR = Repair / Replace URGENT - Needs Immediate Attention NA = Not Applicable

Checklist

1. PPE Check		
1. Are You Wearing Hi-Vis	OK	
2. Are You Wearing Eye Protection	OK	
3. Is The Area You Are Working In Free From Hazard	OK	
4. Is A Hard Hat Required For Work Being Perf	NA	
5. Are You Up To Date With OK Alone	NA	
2. Safety Checks		
1. Tire Condition & Air Pressure	NA	
2. Wheel Nuts & Studs (Torque To Spec)	NA	
3. Frame, Boom & Pins	OK	
4. Counterweight Bolts	NA	
5. Tailgate Latch	OK	
6. Safety Decals	REPAIR	
7. Handles & Steps	REPAIR	
8. Operator Seat	OK	
9. Operator Seat Belt	OK	
10. Operator Seat Bar	OK	
11. Horn Operation	OK	
12. Back Up Alarm	OK	
13. Wiper Motor / Arm / Blade	OK	
14. Warning Beacons & Lights	OK	
15. Boom Stop	REPAIR	
16. Boom Release	OK	
3. Operation Checks		
1. Power Train Performance	OK	
2. Steering Operation	OK	
3. Auxiliary & Hydraulic Operation	OK	
4. Visible Leaks	OK	
4. Engine Checks		
1. Engine Oil And Filter	OK	
2. Air Filter & Inlet	OK	
3. Cooling Package Operation	OK	
4. Coolant Level Check	OK	
5. Coolant Condition	OK	
6. Drive Belt	OK	
7. Ancillary Belts	OK	
8. Clamps & Hardware	OK	
9. Exhaust	OK	
5. Hydraulic System Checks		
1. Oil Level (Boom Down)	OK	
2. All Cylinders For Leaks & Chrome Wear	OK	
3. All Hoses For Leaks, Damage, Wear	OK	
6. Driveline Checks		
1. Chaincase Oil Level & Condition	NA	
2. Axle Check	NA	
3. Axle Bearings & Seals	NA	
4. Pedals & Linkage	REPAIR	
7. Steering Checks		
1. Forward & Reverse Speed	OK	
2. Tracking	OK	
3. Drive Creep	OK	
4. 2 Speed Operation	OK	
8. Electrical System Checks		
1. Check & Clean Battery Terminals	OK	
2. Start & Charging Systems	OK	
3. Instrument Clusters	OK	
4. All Switch Operations	REPAIR	
5. Pull & Save Codes (Report If Any)	NA	
9. Bobtach		
1. Main Pins & Bushings	REPAIR	
2. Tilt Pins & Bushings	REPAIR	
3. Lever Operation	OK	
4. Visible Cracks & Damage	OK	
5. Power Bobtach Operation	OK	

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: 29722
Make: KUBOTA
Model: SVL75-2
Meter: 2792.7
Unit No.: 29722 / Internal No.: 29722

Checklist Comments

Question

Notes/Comments

Section: 2. Safety Checks

6. Safety Decals

Some decals damaged / missing

7. Handles & Steps

Front steps damaged

14. Warning Beacons & Lights

lights working no beacon

15. Boom Stop

Mounting hardware rusted / worn handle cracked recommend replacements

Section: 3. Operation Checks

1. Power Train Performance

Slight grinding type noise , not familiar with these units this may be normal

Section: 4. Engine Checks

1. Engine Oil And Filter

Oil full starting to get dark not sure on history no hours or dates on filters

5. Coolant Condition

-21 deg c

7. Ancillary Belts

A/c belt showing start of wear on edges

Section: 5. Hydraulic System Checks

1. Oil Level (Boom Down)

Just over half way line between add and full

Section: 6. Driveline Checks

4. Pedals & Linkage

Pedal showing signs of ware , sloppy possibly worn bushing

Section: 7. Steering Checks

3. Drive Creep

None noted

Section: 8. Electrical System Checks

1. Check & Clean Battery Terminals

Battery at 12.90V after bringing into shop



**Westerra
Equipment**

A WESGROUP EQUIPMENT COMPANY

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

<https://www.westerraequipment.com/>

Work Order
134535758

Date Completed
2024-06-24

Work Order Type
Service

Person
Todd Richardson

Customer

WESTERRA EQUIPMENT LP - ABB
3349 MT LEHMAN ROAD
ABBOTSFORD, BC V4X 0C2
604-850-7313

Equipment

S/N: 29722
Make: KUBOTA
Model: SVL75-2
Meter: 2792.7
Unit No.: 29722 / Internal No.: 29722

2. Start & Charging Systems

No issues starting , charging system is at 14.3V strong / good

4. All Switch Operations

A/c climate cotroll missing knob

Section: 9. Bobtach

1. Main Pins & Bushings

Showing starting signs of ware and has play

2. Tilt Pins & Bushings

Starting to show signs of ware , has play

3. Lever Operation

Works ok but cylinder mounting points are worn and wiggle
around recommend new cylinder