



A WESGROUP EQUIPMENT COMPANY

<https://www.wesgroupequipment.com>

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
SVO103266

Work Order Type
Service

Date Completed
2024-09-16

Person
Rene Villegas

Customer

COMPACT USED-CAP - ABBOTSFORD
3349 Mt. Lehman Rd
ABBOTSFORD, BC V2T 5M1
778.369.2013

Equipment

S/N: DHKCEBBWCF0001121
Make: DOOSAN (OLD)
Model: DX235LCR
Meter: 5275.0
Unit No.: 107747 / Internal No.: EQ229835

Labels

Shop

Description

PLEASE DO A UEI AS PER GUIDLINESPLEASE DO A UEI AS PER GUIDLINES

Work Performed

The inspection is performed finding multiple faults that need be to repair or adjust. The hydraulic oil tank, the DEF tank and the reservoir tank of the coolant set to the correct level. Hydraulic oil leak is corrected by replacing the o- ring in a hose.

By: Rene Villegas, Date: 2024-09-16

Parts

Date	Description	Quantity
2024-09-16	ANTIFREEZE LEVY 4L (1 GAL)	1.00
2024-09-16	DIESEL EXHAUST FLUID 9.46 L	2.00
2024-09-16	ANTIFREEZE/COOLANT EG PRE MIX GAL	1.00

Travel & Labor

Date	Person	Type
2024-09-16	Rene Villegas	LABOR

Customer Name: Kourtney Vitcoe

By signing below, the signer agrees the work above has been completed. The customer will receive an invoice separately which is due and payable as per the terms specified. Thank you for your business!

Kourtney Vitcoe



A WESGROUP EQUIPMENT COMPANY

3349 Mt. Lehman Rd
Abbotsford, BC V2T 5M1
778-369-2013

Work Order
SVO103266

Date Completed
2024-09-16

<https://www.wesgroupequipment.com>

Work Order Type
Service

Person
Rene Villegas

Customer

COMPACT USED-CAP - ABBOTSFORD
3349 Mt. Lehman Rd
ABBOTSFORD, BC V2T 5M1
778.369.2013

Equipment

S/N: DHKCEBBWCF0001121
Make: DOOSAN (OLD)
Model: DX235LCR
Meter: 5275.0
Unit No.: 107747 / Internal No.: EQ229835

OK = Completed & OK

ADJUST = Adjustment Needed

REPAIR = Repair / Replace

URGENT - Needs Immediate Attention

NA = Not Applicable

Checklist

1. PPE Check

- 1. Are You Wearing Hi-Vis OK
- 2. Are You Wearing Eye Protection OK
- 3. Is The Area You Are Working In Free From Hazard OK
- 4. Is A Hard Hat Required For Work Being Performed OK
- 5. Are You Up To Date With OK Alone OK

2. Safety Checks

- 1. Hydraulic Lock Out Function OK
- 2. Cab Condition OK
- 3. Workgroup OK
- 4. Wedge Coupler Lock Installed (if equipped) REPAIR
- 5. Counterweight Bolts OK
- 6. Compartment Latches OK
- 7. Safety Decals OK
- 8. Handles & Steps REPAIR
- 9. Operator Seat OK
- 10. Operator Seat Belt OK
- 11. Operator Door Secured OK
- 12. Horn Operation OK
- 13. Wiper Motor / Arm / Blade REPAIR
- 14. Travel Alarm OK
- 15. Warning Beacons & Lights OK

3. Operation Checks

- 1. Power Train Performance OK
- 2. Steering Operation OK
- 3. Auxiliary & Hydraulic Operation OK
- 4. Visible Leaks OK

4. Engine Checks

- 1. Engine Oil And Filter OK
- 2. Air Filter & Inlet OK
- 3. Cooling Package Operation OK
- 4. Coolant Level Check OK
- 5. Coolant Condition OK
- 6. SCR Condition OK
- 7. Ancillary Belts OK
- 8. Clamps & Hardware OK
- 9. Exhaust OK

5. Hydraulic System Checks

- 1. Oil Level (All Cylinders Retracted) ADJUST
- 2. All Cylinders For Leaks & Chrome Wear REPAIR
- 3. All Hoses For Leaks, Damage, Wear REPAIR

6. Driveline Checks

- 1. Sprocket Check OK
- 2. Track Check REPAIR
- 3. Idlers Check OK
- 4. Rollers Check OK
- 5. House Swing Operation OK
- 6. Rotex Bearing OK
- 7. Forward & Reverse Speed OK

7. Steering Checks

- 1. Tracking OK
- 2. Travel Lever Check OK
- 3. 2 Speed Operation OK

8. Electrical System Checks

- 1. Check & Clean Battery Terminals OK
- 2. Start & Charging Systems OK
- 3. Instrument Clusters OK
- 4. Radio Operation REPAIR
- 5. All Switch Operations OK
- 6. Telematics Reporting / Update Filter Reset OK
- 7. Pull & Save Codes (Report If Any) OK

9. Structural

- 1. Main Pins & Bushings REPAIR
- 2. Stick Pins & Bushings OK
- 3. Coupler Pins & Bushings OK
- 4. Visible Cracks & Damage OK

Customer

COMPACT USED-CAP - ABBOTSFORD
3349 Mt. Lehman Rd
ABBOTSFORD, BC V2T 5M1
778.369.2013

Equipment

S/N: DHKCEBBWCF0001121
Make: DOOSAN (OLD)
Model: DX235LCR
Meter: 5275.0
Unit No.: 107747 / Internal No.: EQ229835

Checklist Comments

Question

Notes/Comments

Section: 2. Safety Checks

4. Wedge Coupler Lock Installed (if equipped)

The safety lock is not installed and I search it inside the cabin, but it is not there either

8. Handles & Steps

The step is bent and needs to be welded

13. Wiper Motor / Arm / Blade

Not working

Section: 4. Engine Checks

4. Coolant Level Check

It is necessary to add coolant

6. SCR Condition

It's necessary to add DEF

Section: 5. Hydraulic System Checks

1. Oil Level (All Cylinders Retracted)

It is necessary to add oil

2. All Cylinders For Leaks & Chrome Wear

The bucket rod is damaged

3. All Hoses For Leaks, Damage, Wear

Fixed

Section: 6. Driveline Checks

2. Track Check

4 bolts for the tracks shoes need to be re-tightened or replace and one bolt that was lost needs to be installed

Section: 8. Electrical System Checks

4. Radio Operation

The radio turns on and off, but the speakers can not be heard.

Section: 9. Structural

1. Main Pins & Bushings

It is necessary to repair the main boom pin housing as well as replaced the lift cylinder bushings and pins